



Positions:

- Pos. 1) 1x Drilling
- Supply lines - A1000 (B)
 - Supply lines - SU12 (A)
- Pos. 2) 1x Drilling (Option)
- Coffee-grounds ejection - A1000 (B)
- Pos. 3) 8x Surface
- Equipement feet



