






## Definicje faz

Nr st. zewn.	1	2	3	4
Nr O KP				
Nr O SR				
Nazwa skrócona	Faza 1 Lwow	Faza 2 War	Faza 3 Pod W	Faza 4 Pod E
Nazwa	Faza 1 Lwow	Faza 2 War	Faza 3 Pod W	Faza 4 Pod E
Opis				
CS SW	CS SW 1	CS SW 1	CS SW 1	CS SW 1
K1	⊖	●	⊖	⊖
K2P	⊖	●	⊖	⊖
K2	⊖	⊖	⊖	●
K3	●	⊖	⊖	⊖
K4	⊖	⊖	●	⊖
PR1	⊖	⊖	⊖	●
PR2	⊖	⊖	⊖	●
P4	●	⊖	⊖	⊖
P5	●	⊖	⊖	⊖
P7	⊖	⊖	●	⊖
P8	⊖	⊖	●	⊖
PR10	⊖	●	⊖	⊖
PR11	⊖	●	⊖	⊖
S1	⊖	⊖	●	⊖
S2	⊖	⊖	●	●
S3	⊖	⊖	●	●
S4	●	⊖	●	⊖
O1	⊖	⊖	⊖	⊖
O2	⊖	⊖	⊖	⊖
O3	⊖	⊖	⊖	⊖
O4	⊖	⊖	⊖	⊖



Schemat zmian faz: PFP 1



Tablica: PFP 1

		Do fazy			
		Faza 1	Faza 2	Faza 3	Faza 4
Od fazy	Faza 1 Lwow		x		
	Faza 2 War			x	
	Faza 3 Pod W				x
	Faza 4 Pod E	x			