

**„Wsparcie przy rewizji hydroakumulatorów na FW Ostaszewo (20 turbin Vestas V110 2MW)”**

**WYKAZ HYDROAKUMULATORÓW:**

Lp.	Nr ewidencyjny	Typ	Nr fabryczny Nr technologiczny
1	<b>23</b> 06 038329	ACL	14D143110 204640
2	<b>23</b> 06 038330	ACL	14D143113 204640
3	<b>23</b> 06 038331	ACL	14D143029 204640
4	<b>23</b> 06 038332	ACL	14D143150 204640
5	<b>23</b> 06 038333	ACL	14D145016 204641
6	<b>23</b> 06 038334	ACL	14D143010 204641
7	<b>23</b> 06 038335	ACL	14D144127 204641
8	<b>23</b> 06 038336	ACL	14D144104 204641
9	<b>23</b> 06 038337	ACL	14D143033 204642
10	<b>23</b> 06 038338	ACL	14D143167 204642
11	<b>23</b> 06 038339	ACL	14D143151 204642
12	<b>23</b> 06 038340	ACL	14D143170 204642
13	<b>23</b> 06 038341	ACL	14D144019 204643
14	<b>23</b> 06 038342	ACL	14D143043 204643
15	<b>23</b> 06 038343	ACL	14D144009 204643
16	<b>23</b> 06 038345	ACL	14D143046 204644
17	<b>23</b> 06 038346	ACL	14D143052 204644
18	<b>23</b> 06 038347	ACL	14D143190 204644
19	<b>23</b> 06 038348	ACL	14D143045 204644
20	<b>23</b> 06 038349	ACL	B666107 204645
21	<b>23</b> 06 038350	ACL	B666102 204645
22	<b>23</b> 06 038351	ACL	14D143035 204645

23	<b>23</b> 06 038352	ACL	14D143152 204645
24	<b>23</b> 06 038353	ACL	14D143176 204646
25	<b>23</b> 06 038354	ACL	14D143081 204646
26	<b>23</b> 06 038355	ACL	14D143175 204646
27	<b>23</b> 06 038356	ACL	14D143074 204646
28	<b>23</b> 06 038357	ACL	B641031 204647
29	<b>23</b> 06 038358	ACL	B622012 204647
30	<b>23</b> 06 038359	ACL	B622056 204647
31	<b>23</b> 06 038360	ACL	B622073 204647
32	<b>23</b> 06 038361	ACL	14D144158 204648
33	<b>23</b> 06 038362	ACL	14D144129 204648
34	<b>23</b> 06 038363	ACL	B683118 204648
35	<b>23</b> 06 038364	ACL	B683002 204648
36	<b>23</b> 06 038365	ACL	14D143022 204649
37	<b>23</b> 06 038366	ACL	14D143060 204649
38	<b>23</b> 06 038367	ACL	14D143064 204649
39	<b>23</b> 06 038368	ACL	14D145005 204649
40	<b>23</b> 06 038369	ACL	B663007 204650
41	<b>23</b> 06 038370	ACL	B656065 204650
42	<b>23</b> 06 038371	ACL	B622021 204650
43	<b>23</b> 06 038372	ACL	B663068 204650
44	<b>23</b> 06 038373	ACL	14D143019 204651
45	<b>23</b> 06 038374	ACL	14D143021 204651
46	<b>23</b> 06 038375	ACL	14D143058 204651

47	<b>23</b>	06 038376	ACL	<u>14D143136</u> 204651
48	<b>23</b>	06 038377	ACL	<u>14D144071</u> 204652
49	<b>23</b>	06 038378	ACL	<u>14D144105</u> 204652
50	<b>23</b>	06 038379	ACL	<u>14D144008</u> 204652
51	<b>23</b>	06 038380	ACL	<u>14D144154</u> 204652
52	<b>23</b>	06 038381	ACL	<u>B666096</u> 204653
53	<b>23</b>	06 038382	ACL	<u>B673002</u> 204653
54	<b>23</b>	06 038383	ACL	<u>14D143012</u> 204653
55	<b>23</b>	06 038384	ACL	<u>B666050</u> 204653
56	<b>23</b>	06 038385	ACL	<u>14D144025</u> 204654
57	<b>23</b>	06 038386	ACL	<u>14D143101</u> 204654
58	<b>23</b>	06 038387	ACL	<u>14D143075</u> 204654
59	<b>23</b>	06 038388	ACL	<u>14D143056</u> 204654
60	<b>23</b>	06 038389	ACL	<u>B641018</u> 204655
61	<b>23</b>	06 038390	ACL	<u>B641025</u> 204655
62	<b>23</b>	06 038391	ACL	<u>B622148</u> 204655
63	<b>23</b>	06 038392	ACL	<u>B641001</u> 204655
64	<b>23</b>	06 038393	ACL	<u>B666041</u> 204656
65	<b>23</b>	06 038394	ACL	<u>B666056</u> 204656
66	<b>23</b>	06 038395	ACL	<u>B681137</u> 204656
67	<b>23</b>	06 038396	ACL	<u>B622072</u> 204656
68	<b>23</b>	06 038397	ACL	<u>14D143082</u> 204657
69	<b>23</b>	06 038398	ACL	<u>14D143196</u> 204657
70	<b>23</b>	06 038399	ACL	<u>14D143039</u> 204657

71	<b>23</b> 06 038400	ACL	<u>14D143048</u> 204657
72	<b>23</b> 06 038401	ACL	<u>14D144043</u> 204658
73	<b>23</b> 06 038402	ACL	<u>14D144044</u> 204658
74	<b>23</b> 06 038403	ACL	<u>14D144145</u> 204658
75	<b>23</b> 06 038405	ACL	<u>B681169</u> 204659
76	<b>23</b> 06 038406	ACL	<u>B681151</u> 204659
77	<b>23</b> 06 038407	ACL	<u>14D143080</u> 204659
78	<b>23</b> 06 038408	ACL	<u>B666034</u> 204659
79	<b>23</b> 06 048387	ACL 201	<u>21D297170</u> 204658
80	<b>23</b> 06 068748	ACL	<u>J837030</u> 204643