



WARIANT	Dz	t	L	l1	h	w	d1	d2
I	$\varnothing 38.0$	5.0	> 150	10	0,75	1	1	1
II	$\varnothing 44.5$	5.0	> 150	10	0,75	1	1	1
III	$\varnothing 51.0$	4.0	> 150	10	0,75	1	1	1

- 1) Tolerancja dla otw. i rowków:  $\pm 10\%$
- 2) Gat. 13CrMo4-5 (15HM)

$Ra\ 3,2$  (✓)